



INFORMATION BULLETIN 30/2005

TO : ALL U.A.E. B767 OPERATORS
FROM: DIRECTOR AVIATION SAFETY AND SECURITY
REF: 20212/6101
DATE: 27TH DECEMBER 2005
SUBJECT: BOEING SERVICE BULLETIN NO.767-24-0160 DATED 30TH JUNE 2005
STATUS: URGENT

The purpose of this Information Bulletin is to inform all U.A.E. operators operating the B767 aircraft on the removal and replacement of the Static Inverter module.

Boeing has recommended that operators comply with the above mentioned Service Bulletin within 42 months or less from the release date of the Service Bulletin. However, following two (2) incidents involving Static Inverter Overheat that occurred on the B767 aircraft operated by Air Atlanta Icelandic, the GCAA hereby requires that all U.A.E. B767 operators immediately replace existing Static Inverters with new or changed Static Inverters as recommended by the above Service Bulletin.

All concerned operators are to inform the GCAA upon completion of the required modification as recommended by the Service Bulletin.

This Information Bulletin is issued for your attention and necessary action.

Best regards,

AHMED AL HADDABI
DIRECTOR AVIATION SAFETY AND SECURITY

