



## Information Bulletin Number 24/2004

**TO : ALL UAE OPERATORS**  
**FROM : DIRECTOR FLIGHT SAFETY & SECURITY**  
**REF. : 20212/3299/04**  
**DATE : TUESDAY, JULY 27, 2004**  
**SUBJECT : ENGINE OUT DURING FLIGHT TEST**

This is to bring to your attention that during a recent review of the flight test schedule used by UAE operators for the purpose of annual flight test of UAE registered multi-engine aircraft it was observed that some of the Test Flights Schedules called for an engine out during en-route climb for 5 minutes.

Kindly be advised that this test is not mandated by the UAE CARs Part V Chapter 3 Section 10, therefore all operators of UAE registered aircraft shall refrain from conducting this test during the annual test flight unless recommended by the aircraft manufacturer or Type Certificate issuing authority and approved by this authority.

Best regards,



**MOHAMED GHANIM AL GHAITH**  
**DIRECTOR GENERAL**